

APPENDIX B

REGION 5 HAZARD MITIGATION PLAN MAPS, FIGURES AND TABLES

Geological Hazards	
Map, Figure or Table Title	Page Number
<u>AVALANCHE</u>	
Figure 4.G1-1 Slab Avalanche	Pg 4.G1-3
Map 4.G1-1 Areas Vulnerable to Avalanche	Pg 4.G1-5
Table 4.G1-1 Pierce County Avalanches of Record	Pg 4.G1-7
<u>EARTHQUAKE</u>	
Figure 4.G2-1 Types of Earthquakes	Pg 4.G2-2
Map 4.G2-1 Major Faults in the Puget Sound Basin Pg 4.G2-4	Pg 4.G2-4
Map 4.G2-2 Seattle and Tacoma Fault Segments	Pg 4.G2-5
Map4.G2-3 Pierce County Seismic Hazard	Pg 4.G2-7
Map4.G2-3 Pierce County Seismic Hazard	Pg 4.G2-7
Table 4.G2-1 Notable Earthquakes Felt in Pierce County	Pg 4.G2-9
Figure 4.G2-2 Salmon Beach, Tacoma Washington – Following Feb. 2001 Earthquake	Pg 4.G2-11
Figure 4.G2-3 Liquefaction, Niigata Japan 1964	Pg 4.G2-14
Figure 4.G2-4 Lateral Spreading – March 2001	Pg 4.G2-14
<u>LANDSLIDE</u>	
Figure 4.G3-1 Northeast Tacoma – Landslide 01/2007	Pg 4.G3-2
Map 4.G3-1 Pierce County Landslide and Soil Erosion Hazard	Pg 4.G3-4
Map 4.G3-2 Pierce County Shoreline Slope Stability Areas	Pg 4.G3-5
Table 4.G3-1 Notable Landslides in Pierce County	Pg 4.G3-6
Figure 4.G3-2 Ski Park Road – Landslide 01/31/03	Pg 4.G3-7
Figure 4.G3-3 SR-165 Bridge Along Carbon River – Landslide 2/1996	Pg 4.G3-8
Figure 4.G3-4 Aldercrest Drive – Landslide	Pg 4.G3-9

Geological Hazards	
Map, Figure or Table Title	Page Number
<u>TSUNAMI</u>	
Figure 4.G4-1 Hawaii 1957 – Residents Explore Ocean Floor Before Tsunami	Pg 4.G4-2
Figure 4.G4-2 Hawaii 1949 – Wave Overtakes a Seawall	Pg 4.G4-3
Figure 4.G4-3 Puget Sound Fault Zone Locations, Vertical Deformations, and Peak Ground Acceleration	Pg 4.G4-5
Figure 4.G4-4 Seattle and Tacoma Faults	Pg 4.G4-6
Figure 4.G4-5 Tsunami Inundation and Current Based on Earthquake Scenario	Pg 4.G4-7
Figure 4.G4-6 Puget Sound Landslide Areas and Corresponding Tsunamis	Pg 4.G4-9
Figure 4.G4-7 Puget Sound River Deltas, Tsunami Evidence, and Peak Ground Acceleration	Pg 4.G4-10
Figure 4.G4-8 Salmon Beach, Pierce County, 1949 – Tsunamigenic Subaerial Landslide	Pg 4.G4-12
Figure 4.G4-9 Puyallup River Delta – Submarine Landslides	Pg 4.G4-14
Figure 4.G4-10 Puyallup River Delta – Submarine Landslides and Scarp	Pg 4.G4-15
Figure 4.G4-11 Damage in Tacoma from the 1894 Tsunami	Pg 4.G4-17
<u>VOLCANIC</u>	
Figure 4.G5-1 Volcanic Hazards	Pg 4.G5-2
Figure 4.G5-2 Debris flow at Tahoma Creek, July 26,1988	Pg 4.G5-3
Figure 4.G5-3 Douglas Fir Stump – Electron Lahar Deposit in Orting	Pg 4.G5-3
Figure 4.G5-4 Landslide from Little Tahoma Peak Covering Emmons Glacier	Pg 4.G5-4
Table 4.G5-1 Tephra Types and Sizes	Pg 4.G5-5
Map 4.G5-1 Lahars, Lava Flows, and Pyroclastic Hazards of Mt. Rainier	Pg 4.G5-6
Table 4.G5-2 Estimated Lahar Travel Times for Lahars 10(7) to 10(8) Cubic Meters in Volume	Pg 4.G5-8
Map 4.G5-2 Ashfall Probability From Mt. Rainier Pg 4.G5-9	Pg 4.G5-9
Map 4.G5-3 Annual Probability of 10 Centimeters or more of Tephra Accumulation in the Pacific NW	Pg 4.G5-9
Figure 4.G5-5 Cascade Eruptions	Pg 4.G5-10
Table 4.G5-4 Mt. Rainier Identified Tephra, last 10,000 years	Pg 4.G5-10
Table 4.G5-5 Pierce County River Valley Debris Flow History	Pg 4.G5-11

Meteorological Hazards	
Map, Figure or Table Title	Page Number
<u>CLIMATE CHANGE</u>	
Figure 4.M1-1 Global Temperature Change: 1850 to 2006	Pg 4.M1-2
Table 4.M1-1 Recent and Projected Temperatures for the Pacific Northwest	Pg 4.M1-5
Figure 4.M1-2 Comparison of the South Cascade Glacier: 1928 to 2003	Pg 4.M1-9
Figure 4.M1-3 Lower Nisqually Glacier Retreat: 1912 to 2001	Pg 4.M1-10
<u>DROUGHT</u>	
Figure 4.M2-1 Sequence of Drought Impacts	Pg 4.M2-3
Table 4.M2-1 Palmer Drought Severity Index	Pg 4.M2-4
Map 4.M2-1 Pierce County Watersheds	Pg 4.M2-5
Figure 4.M2-2 % Area of Basin in Drought Conditions Since 1895	Pg 4.M2-6
Map 4.M2-2 % of Time in Severe to Extreme Drought: 1895-1995	Pg 4.M2-7
Map 4.M2-3 % of Time in Severe to Extreme Drought: 1985-1995	Pg 4.M2-7
Table 4.M2-2 Notable Droughts Affecting Pierce County	Pg 4.M2-8
Map 4.M2-4 Columbia River Basin	Pg 4.M2-10
Map 4.M2-5 USDA Climate Zones – Washington State	Pg 4.M2-14
<u>FLOOD</u>	
Map 4.M3-1 Pierce County Watersheds	Pg 4.M3-4
Map 4.M3-2 Pierce County Flood Hazard	Pg 4.M3-5
Map 4.M3-3 Pierce County Repetitive Loss Areas	Pg 4.M3-6
Map 4.M3-4 Clear Creek Basin	Pg 4.M3-9
Map 4.M3-5 Repetitive Flood Loss Aerial Photo	Pg 4.M3-10
Table 4.M3-1 Flood Hazard Declared Disasters Pg 4.M3-13	Pg 4.M3-13
Figure 4.M3-1 Feb 8, 1996 Flooding – Del Rio Mobile Homes Along Puyallup River	Pg 4.M3-14
Figure 4.M3-2 Nov. 2006 Flooding River Park Estates – Along Puyallup River	Pg 4.M3-16
Figure 4.M3-3 Nov. 2006 Flooding State Route 410 – Along Puyallup River	Pg 4.M3-18
Figure 4.M3-4 Nov. 2006 Flooding Rainier Manor – Along Puyallup River	Pg 4.M3-19
<u>SEVERE WEATHER</u>	
Table 4.M4-1 Fujita Tornado Damage Scale	Pg 4.M4-3
Figure 4.M4-1 Windstorm Tracks Pg 4.M4-4	Pg 4.M4-4

Meteorological Hazards	
Map, Figure or Table Title	Page Number
Map 4.M4-1 Pierce County Severe Weather Wind Hazard – South Wind Event	Pg 4.M4-5
Map 4.M4-2 Pierce County Severe Weather Wind Hazard – East Wind Event	Pg 4.M4-6
Table 4.M4-2 Notable Severe Weather in Pierce County	Pg 4.M4-7 & 8
Figure 4.M4-2 Snowstorm 01/2004 Downtown Tacoma	Pg 4.M4-10
Figure 4.M4-3 Satellite Image – Hanukkah Eve Windstorm	Pg 4.M4-11
Figure 4.M4-4 Before/After Tornado Damage Greensburg, KS 05/04/07	Pg 4.M4-13
Figure 4.M4-5 Public Works Responds 2005 Snowstorm	Pg 4.M4-14
Figure 4.M4-6 Downed Power Pole 02/2006 Windstorm	Pg 4.M4-17
Figure 4.M4-7 County Road December 2006 Windstorm	Pg 4.M4-19
Figure 4.M4-8 Tacoma Narrows Bridge – November 7, 1940 Windstorm	Pg 4.M4-22
<u>WILDLAND URBAN INTERFACE FIRE</u>	
Map 4.M5-1 Washington State Fire Hazard Map Pg 4.M5-3	Pg 4.M5-3
Map 4.M5-2 Pierce County Forest Canopy	Pg4.M5-4
Map 4.M5-3 Industrial Fire Precaution Level Shutdown Zones	Pg 4.M5-5
Figure 4.M5-1 Carbon Copy Fire August 2006	Pg 4.M5-6
Map 4.M5-4 Washington State DNR Wildland Fire Statistics: 1973-2007	Pg 4.M5-7
Table 4.M5-1 DNR Wildland Response South Puget Sound Region: 2002-2007	Pg 4.M5-7
Table 4.M5-2 Pierce County DNR Fires	Pg 4.M5-8